

FIG. 1




FIG. 2A




FIG. 2B

DEFECT SIGNAL

H

L

The figure shows a square wave representing a defect signal. The high level is labeled 'H' and the low level is labeled 'L'. The signal transitions from high to low at a specific point, indicated by a vertical dashed line.

FIG. 2C

FE SIGNAL

The figure shows a sinusoidal waveform representing an FE signal. A vertical dashed line is drawn through the center of the waveform.

FIG. 2D

FOCUS DRIVE SIGNAL

The figure shows a sinusoidal waveform representing a focus drive signal. A vertical dashed line is drawn through the center of the waveform.

FIG. 2E

TE SIGNAL

The figure shows a sinusoidal waveform representing a TE signal. A vertical dashed line is drawn through the center of the waveform.

FIG. 2F

TRACKING DRIVE SIGNAL

The figure shows a sinusoidal waveform representing a tracking drive signal. A vertical dashed line is drawn through the center of the waveform.

FIG. 3A DEFECT SIGNAL



FIG. 3B FE SIGNAL




FIG. 3C FOCUS DRIVE SIGNAL



FIG. 3D TE SIGNAL



FIG. 3E TRACKING DRIVE SIGNAL







FIG. 5



10007276-11201




FIG. 7A DEFECT
SIGNAL



FIG. 7B FE SIGNAL



FIG. 7C FOCUS
DRIVE SIGNAL



FIG. 7D TE SIGNAL



FIG. 7E TRACKING
DRIVE SIGNAL

